Date:

Thursday, 13/11/2008 7:48:04 AM

User

Linda Lacelle

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 43402

Estimate Number

: 12897

P.O. Number

Checked & Approved By

: 13/11/2008 This Issue

: NC Prsht Rev.

First Issue **Previous Run**

Written By

Comment

: 11

: 43198

S.O. No. :

: LARGE FAB ASSY

Type

: Est Rev:A

New Issue 07-06-09 JLM **Drawing Name**

Drawing Number

: STEP HI LONG

Part Number

: D32721

: B

: D3272 REV B : N/A

Project Number Drawing Revision

Material

Due Date : 21/11/2008 Qty:

Each Um:

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

D2622120C

1.0000 Each(s)/Unit

Step Extrusion

8.0000 Each(s)

Comment: Qty.: Pick:

Qty Part Number

Description Batch

Total:

D2622-120

Extrusion 42155

10

2.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

1-Cut D2622-120 extrusion to 116.25" long as per Dwg D3272 using cutting table setup DT 8185-2A

2-Drill extrusion as per Dwg D3272 using Jig DT8680 for rivets.

3-Deburr

INSPECT WORK TO CURRENT STEP

SAD

3.0

QC5

Comment: INSPECT

PACKAGING 1

0611.13



WORK TO CURRENT STEP

4.0

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock Location: WA



Dart Ae	rospace	Ltd							
W/O:			W	ORK ORDER CHANG	GES				
DATE	STEP	PRO	PROCEDURE CHANGE			Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cat	egory:	NCR:	: Yes N	o DQA :	Date: _	
	Re	esolution:	Dispositi	on:	QA: I	N/C Clos	sed:	Date: _	
NCR:		\	WORK ORI	DER NON-CONFORM	IANCE	(NCR)			
DATE	STEP	Description of NC		Corrective Action Se			Verification	1 Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section C	Chief Eng	QC Inspector

NCR:			WORK ORDE	ER NON-CONFORMANO	E (NCR)			
		Description of NC	Corrective Action Section B			Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
]	

NOTE: Date & initial all entries

Date: User:

Thursday, 13/11/2008 7:48:04 AM

Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: STEP HI LONG

Job Number: 43402

Part Number: D32721

Job Number:



Seq. #:

Machine Or Operation:

Description:

5.0

QC21

FINAL INSPECTION/W/O RELEASE



08/11/14 AJ

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



Dart Aerospac	e Ltd	
---------------	-------	--

		WORK ORDER CHANGES								
ГЕР	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
						•				
	EP	EP PROCEDURE CHANGE	EP PROCEDURE CHANGE By	EP PROCEDURE CHANGE By Date	EP PROCEDURE CHANGE By Date Qty					


Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
Resolution	on:	Disposition:	QA: N/C Closed	:	Date:

NCR:			WORK ORDE	R NON-CONFORMAN	CE (NCR)			
DATE ST		Description of NC		Corrective Action Section B			Annroyal	Anneoval
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector
	f				1	1		

NOTE: Date & initial all entries



DESIG	^N P	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CANA	
CHEC	KED	APPROVED	DRAWING NO.	REV. B
4	E	世	D3272	SHEET 1 OF 3
DATE			TITLE	SCALE
07.0	05.18		STEP ASSEMBLY, HI LONG	NTS
Α		04.03.01	NEW ISSUE	
В		07.05.18	D3272-1 WAS D2622-120	



QTY	-		
-041	-042	PART NUMBER	DESCRIPTION
X		D3272-041	STEP ASSEMBLY, HIGH LONG (LH)
	Х	D3272-042	STEP ASSEMBLY, HIGH LONG (RH)
1	1	D3065-041	LEG ASSEMBLY
2	2	D3066-1	SPACER
2	2	D3067-1	END PLATE
2	2	D3219-1	SUPPORT
1	1	D3272-1	STEP
<u> </u>			
16	16	MS20600AD4W4	RIVET

GENERAL NOTES:

- 1) D3272-041 SHOWN. FOR D3272-042, INSTALL D3219-1 SUPPORT OPPOSITE SIDE
- 2) WELD PER DART QSI 004
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005.4.1 POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3 **BLACK ANTI-SKID PAINT PER DART QSI 005 4.4**
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- 5) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED.
- 6) BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX.

Dart Aerospace Ltd

W/O:			WORK ORDER	CHANGES	-			
DATE	STEP		PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								<u> </u>
Part No	:	PAR #:	Fault Category:	NCR: Ye	s No DQ	A:	Date: _	
	R	Resolution:	Disposition:	QA: N/C	Closed:		Date: _	

NCR:		V	VORK ORD	DER NON-CONFORMANO	CE (NCR)			
		STED Description of NC		Corrective Action Section B		Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspecto
							\$	
			-					

NOTE: Date & initial all entries

D3272


SHEET


N SCALE 아 3

킕

DRAWING NO

RT AEROSPACE I





¥


PURPOSE


S

COPIED



DESIGN	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CA	
CHECKED	APPROVED	DRAWING NO. D3272	REV. B SHEET 3 OF 3
DATE		TITLE	SCALE
07.05.18		STEP ASSEMBLY, HI LONG	1:20





Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.